



BIKE	TRIUMPH SPEED TRIPLE 1050	PART NO.	RTR - 66 - SE
YEAR	2008 - 2010	FIT KITS	Z039.20471
NOTES	Use standard fittings where not supplied Remove standard gasket if fitted.	DB-Killer	SCEXDBK23 - (Type V)



Remove original bolts x 2 holding footrest to frame, secure Scorpion bracket between footpeg and frame using supplied M8 x 25mm bolts. Tighten securely, re-check after a short ride.

- 1 Serket Conical Silencer RSC231
- 2 Aluminium Bolt Finisher (Z026.20068)
- 3 M8 x 20mm Cap Head Bolt (Z017.10072)
- 4 Mounting Bracket (Z015.31024) **To be mounted behind footrest top bolts (See note/diagram)**
- 5 M8 x 17mm Washers (Z017.10831)
- 6 2 x M8 x 25mm Cap Head Bolts (Z01710073) **To replace**

original footrest bolts (See note/diagram)

- 7 M8 Nyloc Nut (Z017.10062)
- 8 2 x Springs (Z028.10030)
- 9 Connecting Pipe CP702

E-MARK	BSAU 193a 1990/t3
ISSUE NO.	04
DATE	22/10/2018
AUTHORISED	J.Harkin
CHECKED	

NOTE: ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.



A) Remove original exhaust from bike, taking care to keep all original components in a safe place.

B) Refit Scorpion exhaust as per line diagram above.

C) When fitted take bike for a short ride to ensure all functions are correct.

D) When bike & exhaust are cool enough check all nuts and bolts are still secure.

Box: PLOCK 2

BIKE	TRIUMPH SPEED TRIPLE 1050	PART NO.	RTR - 66 - SE
YEAR	2008 - 2010	FIT KITS	Z039.20471
NOTES	Use standard fittings where not supplied Remove standard gasket if fitted.	FEATURES	

Thank you for purchasing your Scorpion Silencer.

Care of your exhaust: Please refrain from cleaning silencer with heavy solvents or abrasives!

Vielen Dank Für den kauf eines Scorpion Schalldampfers! Pflegehinweis: Bitte verwenden Sie niemals Scheuermittel oder aggressive Reiniger zur Pflege Ihres Auspuffes!

Merci d'avoir choisi un echappement Scorpion.

Entretien de votre silencieux: Ne pas utiliser de solvants ou de produits abrasifs!

"Muchas gracias por adquirir un Silencioso Scorpion. Le recomendamos no limpiar el silencioso con productos abrasivos o aquellos que contengan disolventes."